

03500.017420



Col G
PATENT

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:

SHUICHI MURAKAMI ET AL.

Appln. No.: 10/621,347

Filed: July 18, 2003

For: INK JET RECORDING HEAD

)
: Examiner: Thinh Nguyen
)
: Group Art Unit: 2861
)
: Patent No.: 6,935,723 B2
)
: Issued: August 30, 2005
)
: November 16, 2005

Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

Attention: CERTIFICATE OF CORRECTION BRANCH

*Certificate
NOV 21 2005
of Correction*

REQUEST FOR CERTIFICATE OF
CORRECTION UNDER RULE 323

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form (Form PTO-1050), in duplicate, is enclosed.

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction.

11/17/2005 CNGUYEN 00000074 6935723

01 FC:1811

100.00 0P

NOV 22 2005

Patentees' undersigned attorney may be reached in our Washington, D.C. office by telephone at (202) 530-1010. All correspondence should continue to be directed to our address given below.

Respectfully submitted,



Attorney for Patentees
Douglas W. Pinsky
Registration No. 46,994

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
Facsimile: (212) 218-2200

DWP/lw

DC_MAIN 221493v1

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,935,723 B2

DATED : August 30, 2005

INVENTOR(S) : SHUICHI MURAKAMI ET AL.

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 5

Line 12, "filer" should read --filter--.

COLUMN 7

Line 41, "column" should read --columns--, and "to them" should read --as described here--.

COLUMN 8

Line 6, "suppressed." should read --suppressed--.

COLUMN 9

Line 32, "by" should read --according to--, and "made" should read --made by--.

COLUMN 12

Line 33, "rain" should read --resin--.

Line 63, "demonstrates" should read --demonstrate--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 6,935,723 B2

No. of add'l. copies
@ 30¢ per page



UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,935,723 B2

DATED : August 30, 2005

INVENTOR(S) : SHUICHI MURAKAMI ET AL.

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 5

Line 12, "filer" should read --filter--.

COLUMN 7

Line 41, "column" should read --columns--, and "to them" should read --as described here--.

COLUMN 8

Line 6, "suppressed." should read --suppressed--.

COLUMN 9

Line 32, "by" should read --according to--, and "made" should read --made by--.

COLUMN 12

Line 33, "rain" should read --resin--.

Line 63, "demonstrates" should read --demonstrate--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 6,935,723 B2

No. of add'l. copies
@ 30¢ per page

NOV 22 2005

Form PTO 1050 (Rev. 3-82)

(Form#30) DWP/lw 221498v1

